

Bond Strength

Required materials:

- Masonry prisms
- Reaction frame
- Load applicator
- Load measurer
- Bond wrench testing apparatus
- PPE (Personal Protective Equipment) such as work gloves and safety glasses

Reaction frame, load applicator and measurer:

Instron
825 University Ave.
Norwood, MA 02062-2643

Phone 1-800-473-7838

<http://www.instron.com/>

Bond wrench test apparatus details:

ASTM International
100 Barr Harbor Drive
PO Box C700
West Conshohocken, PA 19428-2959 USA

www.astm.org