

Compressive Strength

Required materials:

- Masonry prisms
- Reaction frame
- Load applicator
- Load measurer
- PPE (Personal Protective Equipment) such as work gloves and safety glasses

Reaction frame, load applicator and measurer:

Tinius Olsen, Inc.
1065 Easton Road
PO Box 1009
Horsham, PA 19044-8009

Phone 1-215-675-7100

Fax 1-215-441-0899

<http://www.tiniusolsen.com/>