

**Direct Design Handbook for Masonry Structures  
(TMS 403-10)**

**ERRATA**

**December 6, 2010**

**Watch <http://www.masonrysociety.org/html/resources/DirectDesign/index.htm> for possible additional errata.**

<b>Page</b>	<b>Section No. or Location</b>	<b>Errata to First Printing (<i>be advised that these corrections have been made to the 2<sup>nd</sup> Printing dated December 6, 2010</i>)</b>
Inside Cover	Foreward to the Reference Guide	Correct the Spelling of Forward so that it reads “Forward to the Reference Guide”
Inside Cover	Forward to the Reference Guide, Step 6	Consistent with the Standard, the equation should not be divided by two so that it reads “ $L_{req} = L_{req1} + L_{req2}$ ”
Page ii, Copyright Page	Abstract	On the tenth line of the Abstract, change “...mapped seismic 0.2 second spectral response accelerations up to <del>4.5</del> g, and mapped seismic 1.0 second spectral response accelerations up to <del>3.0</del> g” to “...mapped seismic 0.2 second spectral response accelerations up to <u>3.0</u> g, and mapped seismic 1.0 second spectral response accelerations up to <u>1.25</u> g.” consistent with Sections 2.1.5 and 2.1.6.
C-3	Figure C1.3-1	Change the reference in the figure from Table J to Table <u>3.2-10</u> .

**Watch <http://www.masonrysociety.org/html/resources/DirectDesign/index.htm> for possible additional errata.**